



## Tech Bulletin

**To:** Tommy Gate Distributors  
**From:** Tommy Gate Company  
**Date:** March 24, 2008  
**Re:** 2007 – Present Sprinter Van Step Bumper Incompatible with Model 650

---

### **2007 – Present Sprinter Van Step Bumper Incompatible with Model 650**

The 2007 – Present Sprinter Van may be equipped with a rear step bumper. **This rear step bumper is not compatible with a Model 650 lift gate.** The bumper consists of two corners and a center section. The center section of **the bumper can be unbolted and replaced with a standard bumper.**

With the standard rear bumper installed, the Model 650 can be installed successfully in both the standard and high roof 2007-present Sprinter Vans.